



2GIG GoControl - Equipment Codes

Equipment Code	Equipment Description	Panel firmware version required
9999	Alarm.com Image Sensor Note: Must be added at the panel	1.10+
1062	2GIG Tilt Sensor	1.19+
1064	2GIG Bypass Sensor	1.14+
1065	2GIG Flood Sensor	1.14+
1066	2GIG Shock Sensor	1.14+
1067	2GIG Repeater	1.19+
0519	HW Glass Break "5853"	1.6+
0530	HW PIR "5894PI"	1.6+
0533	HW PIR "5890"	1.6+
0556	Existing Flood/Temp Sensor	1.6+
0557	HW Heat Sensor "5809"	1.6+



Equipment Code	Equipment Description	Panel firmware version required
0577	Existing Keyfob Remote Note: Must be added through the Partner Portal or MobileTech app	1.6+
0589	HW Smoke "5808W3"	1.6+
0609	Existing Motion Detector	1.6+
0616	Existing Smoke Detector	1.6+
0624	HW Flood Sensor "5821"	1.6+
0637	HW D/W "5816"	1.6+
0655	Existing D/W Contact	1.6+
0692	Existing CO Detector	1.6+
0708	Existing Heat Sensor	1.6+
0859	CO1 CO Detector (Canada)	1.6+
0860	CO1 CO Detector (US)	1.6+
0470	HW R-D/W "5818MNL"	1.6+
0863	2GIG Recessed Door Contact	1.6+
0864	2GIG Glass Break	1.6+



Equipment Code	Equipment Description	Panel firmware version required
0866	2GIG 4-Button Keyfob Remote Note: Must be added through the Partner Portal or MobileTech app	1.6+
0867	2GIG Wireless Keypad Note: Must be added at the panel	1.6+
0868	2GIG Panic Button Remote	1.6+
0869	2GIG PIR with Pet Immunity	1.6+
0871	SMKE1 Smoke Detector (Canada)	1.6+
0872	SMKE1 Smoke Detector (US)	1.6+
0873	2GIG Takeover Module	1.6+
0895	SMTK GE Smoke/Heat Detector (US/Canada)	1.6+
1026	2GIG CO Detector	1.8+
1058	2GIG Smoke Detector	1.8+
1059	2GIG TS1 Wireless Touchscreen Keypad Note: Must be added at the panel	1.8+
1061	Tilt Sensor	1.8+



Equipment Code	Equipment Description	Panel firmware version required
1063	2GIG Doorbell	1.9+
0000	Other	1.6+
0475	Existing Glass Break	1.6+
0491	HW Panic Pendant "5802MN2"	1.6+
0862	2GIG Thin D/W Contact	1.6+

